Work	Orde	r ID	60895
Monday,	July 26,	2010	1:56:00 PM



Page 1

Monday, July 26,	2010 1:56:00 PM									1 450 1
Revision ID:	D4149-041 Crosstube Lug Assembly, Aft		Accept				s	etup Sta		
Start Date: Required Date: Reference:	7/26/2010 Start Qty: 4.0 8/2/2010 Req'd Qty: 4.0	1 125111 2151 1251		Cust Item I						
Approvals:	Process Plan:	Date: 10-7-24 Date:	Tooling: SPC (Y/N):		ate:		R	tun Sta		
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #		Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr									
D4149	В									
100 Mali III III III III Small Fab			0.00			4	510	0/68/	23 (Ý)
Small Fab	Memo 1- Ass	emble as per dwg	0.00					,		
	QC5- Inspect part of	completeness to step on W/O	0.00	108/31				\		
QC Quality Control	Memo		0.00	-(08()		-	- (XV	/)		
120	Identify as per dwg	& Stock Location: 505	0.00					///	, , (G	,)
Packaging Packaging	Memo	1	0.00			-	<u>L E /C</u>	<u> 17 37 3</u>		

W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								·	
Part No	:	PAR #:	Fault Cate	jory:	_ NCR: Yes	No DQ	A :	Date:	
	R	esolution:	Disposition	1:	_ QA: N/C (Closed:	<u> </u>	Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	ļ,		tion B		cation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		ion C	Chief Eng	QC Inspector
ļ									
	}	1							

Work Order ID 60895

Monday, July 26, 2010 1:56:01 PM



Page 2

Item ID:

D4149-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Crosstube Lug Assembly, Aft

Start Date:

7/26/2010

Start Qty: 4.00

Required Date: 8/2/2010 Req'd Qty: 4.00

Operation

Description

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: ____

Date:

QC21- Final Inspection - Work Order Release

Date:_____

Tooling:

Set Up/

Run Hours

SPC (Y/N):

Date: Date:

Start Run

Stop

Sequence ID/

Work Center ID

130

Quality Control

Memo

0.00

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Reject Qty Number

Insp. Stamp

10/08/3 CZ10/8/31

W/O:			WORK ORDER CHANGES								
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								<u> </u>			
Part No	•	PAR #:	Fault Cate	gory:	DQA: Date:						
	R	esolution:	Dispositio	n:	QA: N/C	Closed:		Date: _			
NCR:	:	,	WORK ORD	ER NON-CONFORM	ANCE (NO	CR)					
DATE	STEP	Description of NC			Sign & Verification Appro		erification Approval		Approval		
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sigi Da		Section C	Chief Eng	QC Inspector		
	1										
			·								
	ļ .			,							
								-			

Picklist Print

Monday, July 26, 2010 1:56:04 PM

Work Order ID: 60895

Parent Item: D4149-041

Parent Item Name: Crosstube Lug Assembly, Aft

Start Date: 7/26/2010

Required Date: 8/2/2010

Start Qty: 4.00 Required Qty: 4.00

Comments:

IPP Rev:A 10.06.24 new issue DD verf:EC□ IPP Rev:B 10.07.22 as per revB DD verf:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4149-5		Manufactured	No	B60	D790 D	100 B	Each (23)	0.0000		4	0/08	/23	
/ // // // // // // // // // // // // //		Purchased	No			100	Each	534.0000	3	12	S0/0	8/2	23
		4.			114808 115037	<u>Loc (</u>	Oty 534 164 370	Loc Code	 	12	- -		
03910-1	M III	Manufactured	No		113037	100	Each	24.0000	1 	4	10/08	/23	•
					59349 59708	<u>Loc (</u>	Oty 24 23	Loc Code		4	- -		
04091-1 		Manufactured	No			100	Each	2.0000	1 	4	5/0/0	18/2	3
		e.		<u>Location</u> ST460	60239	<u>Loc (</u>	Otv 2 2	Loc Code	_	\mathcal{B}	6087 - B6100	74 (3 08 (3)	
D4149-1	HI (11)	Manufactured	No			100 B6	Each / 00 9	0.0000 Ex		8	5/0/0	8/2	3

Dart Ae	rospace	e Ltd							
W/O:			V	VORK ORDER CHANGE	S				
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		t.							
						·			,
					į				
Part No):	PAR #:	_ Fault Ca	tegory:	NCR: Yes	No DQ	A :	Date: _	
	R	esolution:	_ Disposit	ion:	QA: N/C CI	osed:		Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (NCF	1)		,	
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector
					·				<u>.</u>
								i I	
		·							

Monday, July 26, 2010 1:56:04 PM


Work Order ID: 60895 Parent Item: D4149-041 Parent Item Name: Crosstube Lug Assembly, Aft Required Date: 8/2/2010 Start Date: 7/26/2010 Start Qty: 4.00 Required Qty: 4.00 D4149-3 Manufactured No 0.0000 Each B61010 Spacer AN3C12A Purchased No Each 44.0000 Bolts Location Loc Qty Loc Code ST351 44 112314 8 114761 22 115016 14 AN4C13A Purchased No 100 Each 104.0000 **BOLT** Location Loc Qty Loc Code ST357 104 113359 3 114108 114442 50 114615 50 MS21043-3 Purchased No 100 2,985.000 Each Nut Location Loc Oty Loc Code FG 76 103691 76 ST301 2909 107280 112314 2905

W/O:			WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	[Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
									·						
····		·:													
Part No	:	PAR #:	PAR #: Fault Category: ution: Disposition:				NCR: Yes No DQA: Date:								
	Re	esolution:	Disposition	II	_ QA: N/C	Clos	ed:		Date: _						
NCR:			WORK ORDE	R NON-CONFORMA	NCE (N	CR)									
		Description of NC		on B		Verific	ation		Approval						
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		ın & ate	Secti		Chief Eng	QC Inspector					
							-								


Monday, July 26, 2010 1:56:04 PM

Work Order ID: 60895 Parent Item: D4149-041 Parent Item Name: Crosstube Lug Assembly, Aft **Start Date: 7/26/2010** Required Date: 8/2/2010 Start Qty: 4.00 Required Qty: 4.00 MS21043-4 Purchased No 100 Each 1,220.000 Nut Location Loc Oty Loc Code FG 40 104603 40 ST301 1180 112492 25 113069 114348 347 114523 500 114784 300 NAS1149C0432R Purchased No 100 Each 724.0000 Washer Location Loc Qty Loc Code ST297 724 134 114292 114742 590 NAS1149C0332R Purchased No 100 Each 3,480.000 Washer Location Loc Qty Loc Code ST297 3480 113524 10 113737 150 115000 3320


ospace	Elu												
		WC	RK ORDER CHANGI	ES					_				
STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
					į.								
•	PAR #·	Fault Cate	gory.	NCR:	Yes N	n DQ	Δ-	Date:					
n						eu		Date					
	'	WORK ORDER NON-CONFORMANCE (NCR)											
0.750	Description of NC	Corrective Action				Verification		Approval	Approval				
SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date			Chief Eng	QC Inspector				
					4,			·					
					્રાત ક								
						5. 							
						-	· · .						
	STEP	:PAR #: Resolution: Description of NC	STEP PROCEDURE CHAR : PAR #: Fault Cate Resolution: Disposition WORK ORDI STEP Description of NC Section A Initial	WORK ORDER CHANGE PROCEDURE CHANGE PROCEDURE CHANGE PAR #: Fault Category: Resolution: Disposition: WORK ORDER NON-CONFORMA STEP Description of NC Section A Corrective Action Section Section A Corrective Action Description	WORK ORDER CHANGES STEP PROCEDURE CHANGE :PAR #:Fault Category:NCR: Resolution:Disposition:QA: NORK ORDER NON-CONFORMANCE (WORK ORDER NON-CONFORMANCE (STEP Description of NC Section A Corrective Action Section B Initial Action Description	STEP PROCEDURE CHANGE By I Fault Category: NCR: Yes Note to the process of the	STEP PROCEDURE CHANGE By Date PROCEDURE CHANGE By Date	STEP PROCEDURE CHANGE By Date Qty PAR #: Fault Category: NCR: Yes No DQA: Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Cinief Eng Chief	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date Qty Approval Chief Eng / Prod Mgr :PAR #:Fault Category:NCR: Yes No DQA:Date: Resolution:Disposition:QA: N/C Closed:Date: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC				




Dart Ae	rospace L	.ta							
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHAN	NGE	Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQA: _	Date: _		
	Res	olution:	Disposition):	_ QA: N/C Cld	osed:			
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR)			
DATE	OTED	Description of NC		Corrective Action Section		Verificatio	n Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector	
			·		:				
					*				
								-	
							İ		




W/O:			WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
										9 9				
Part No		PAR #:												
	Re	esolution:							Date: _					
NCR:		,	WORK ORDER NON-CONFORMANCE (NCR)											
DATE	0.7.5	Description of NC		ion B		Verific	cation	Approval	Approvai					
DATE	STEP	Section A	Initial	Action Description Chief Eng		Sign &								
			Chief Eng	Chier Eng		Date	Section	on C	Chief Eng	QC Inspector				
			Chief Eng	Chilei Eng			Secu	on C	Chief Eng	QC Inspector				
			Chief Eng	Chiel Eng	1		Secti	on C	Chief Eng	QC Inspector				
			Chief Eng	Cillei Eng			Seci	on C	Chief Eng	QC Inspector				
	·		Chief Eng	Cillei Erig			Seci	on C	Chief Eng	QC Inspector				
			Crief Eng	Cillei Erig			Seci	on C	Chief Eng	QC Inspector				
			Chief Eng	Cillel Eng			Seci	on C	Chief Eng	QC Inspector				
			Chief Eng	Cillel Eng			Secil	on C	Chief Eng	QC Inspector				
			Chief Eng	Cillel Erig			Secil	on C	Chief Eng	QC Inspector				



Dart Aeı	rospace	e Ltd								
W/O:			V	VORK ORDER CHAN	NGES					
DATE	STEP	PROC	CEDURE CH	HANGE	В	y I	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					- - - - - - - - - - - - - - - - - - -					
Part No		PAR #:								
	R	esolution:	_ Disposit	tion:	QA: N/	C Clos	ed:		Date:	
NCR:		W	ORK OR	DER NON-CONFOR	MANCE (N	NCR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action S Action Description	Section B	ign &	Verification Section C		Approval Chief Eng	Approval QC Inspector
		Occilona	Chief Eng	Chief Eng		Date			Onlor Ling	go mopostor
	}									



Dart Ae	rospace L	_la							
W/O:			WO	RK ORDER CHANGES	3	-			
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQA	۱:	_ Date: _	
	Res	solution:	Fault Category: NCR: Yes No DQA: Date: Disposition: QA: N/C Closed: Date: WORK ORDER NON-CONFORMANCE (NCR)						
NCR:		,	WORK ORDE	R NON-CONFORMAN	CE (NCR)			
DATE	STEP	Description of NC		В	Verification		Approval	Approval	
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
								1	



Da	art	Ae	ero	SD	ac	e	Ltd
----	-----	----	-----	----	----	---	-----

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							ı
Don't No							L

Part No:	PAR #	:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		. · · ·	WORK ORDE	ER NON-CONFORMANO	CE (NCR)								
DATE ST		Description of NC	Corrective Action Section B			Verification	Approval	Ammuoval					
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector					
·····													
						5							